


KROMSKI & SONS FANTASIA




ASSEMBLY INSTRUCTIONS














wrong




good












50 mm
2"












strong screw




strong screw










MAINTENANCE POINTS FOR LUBRICATE - OIL

METAL SPINDLE SHAFT AT BOTH ENDS
WHERE THE BOBBIN BEARINGS RIDE



THE END OF SPINDLE

FOOTMEN/CRANK LOCATIONS

TREADLE HINGES

